


## UNIVERSITY WORKS DIVISION GROUND FLOOR, LIBRARY BLOCK GURU GOBIND SINGH INDRAPRASTHA UNIVERSITY SECTOR 16-C, DWARKA, NEW DELHI –110 078

Tel: 011- 25302289, 25302291, Fax no. 25302290 website: ipu.ac.in



## Circular

Subject: Safety and Security in Dwarka Campus.

On the recommendation of Committee constituted for the purpose, Competent authority has approved the following measures with regard to Safety and Security in Dwarka Campus:

S. No.	Measures	Action by
1.	There are two toilet blocks at each floor having a maintenance	Chief Warden
	shaft which can be accessed through lockable doors already	and
	provided there. The shaft has maintenance platform at every floor	AR (Security)
	with MS railing of approximately 3'-6" height. Doors are in place	
	but not locked. In case of deliberate intentions this may be a safety	
	hazard. The door should be locked and the key should be in	
	control of security:- Report from Warden of hostels may be	
	obtained.	
2.	Both the collapsible gates provided in central staircase at terrace	Chief Warden
	level should be kept locked:- Report from Warden of hostels may	
	be obtained.	
3.	The users may be appraised that fire escape staircase should be	Chief Warden
	used in case of emergency. Normally central staircase should be	
	used:- Report from Warden of hostels may be obtained.	•
4.	Fire escape doors should be controlled by the security as per the	Chief Warden
	system provided therein: Regular monitoring of CCTV Camera	
	output should be in place to prevent student from approaching	
	terrace in normal circumstances. A dedicated person should be	
	deputed for regular monitoring round the clock. AMC of CCTV	

	system should be put in place to ensure zero downtime.	
5.	Every room has a balcony with MS railing of around 3' - 6'	Chief Warden
	height: Room occupants should be advised not to sit or climb or	
	the railings. Details of Advisory/Notices issued to students may be	
	sought from warden. Advisory should be printed and permanently	,
	fixed in such areas.	
6.	Advisory may be issued to students not to visit terraces of school	Proctor
	buildings in normal circumstances and same shall be printed and	
	fixed at such areas.	Dy Reg (GA)
7.	CCTV cameras should be fixed at terrace of school buildings,	Prof. C.S. Ra
	Library and Admin Block.	*Chairman, Committee
		CCTV Procurement
		Incharge (Purchase)
8.	Checking and strengthening of railings in corridors and staircases of school buildings.	EE/UWD
9.	Lighting arrangement in dark areas in University Campus.	EE/UWD
10.		
10.	CCTV installation in Campus, lifts, main gate and terraces.	Prof. C.S. Rai
		Chairman, Committee
		CCTV Procurement
21.10	~	Incharge (Purchase)
11.	Covering of opening in bridge connecting hostels with grills.	EE/UWD
12.		EE/UWD
	Manning of parking spaces.	Incharge Security
13.	Covering of open storm water drains.	EE/UWD
14.	Fire control room/Lift control room should be manned round the clock.	Incharge Security
15.	An expert Committee is constituted for safety audit of the	Safety Security
-	Campus. The Committee will identify the points of concern vis-à-	Safety Security
	vis safety of students/ staff/visitors and suggest remedial action.	Committee
		1. Prof/ C.S. Rai,
1		2 Prof Possis Class
		2. Prof. Pravin Chandra
		Prof. Pravin Chandra     Prof Anup Beniwal,

William Commence

Action taken report on above points may be submitted within 15 days.

(Satnam Singh) Registrar

## Copy for information to:-

- 1. AR, VC Sectt., GGSIPU for kind information of Hon'ble Vice Chancellor.
- 2. SO to Pro VC- for kind information of Pro VC
- 3. Chief Warden
- Proctor
   Prof. C.S. Rai
- 6. Prof. Pravin Chandra
- 7. Dy. Registrar, GA,
- 8. Incharge (Purchase)
- 9. EE/UWD

10. Incharge UITS- To upload on University website

11. Office Copy

(Dr. Vija<del>y Kum</del>ar)

Assistant-Registrar (Security)